

CERTIFICATE OF COMPLIANCE

Certificate Number 20141219-EX26467
Report Reference EX26467-20141218
Issue Date 2014-DECEMBER-19

Issued to: Shandong Jintong Pipeline Co Ltd
No. 6, Yuhe Industrial Park
Weifang
Shandong 261057 CHINA

This is to certify that
representative samples of

FITTINGS, GROOVED AND PLAIN END
Grooved end ductile iron fittings
XGQT01, XGQT02, XGQT021, XGQT022, XGQT03,
XGQT04, XGQT04S, XGQT05, XGQT051, XGQT051S,
XGQT06, XGQT07, XGQT07P, XGQT07S, XGQT08

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 213C, Grooved and Plain End Fittings
ULC/ORD 213, Rubber Gasketed Fittings for Fire-
Protection Service

Additional Information: See the UL Online Certifications Directory at
www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.

Barclay

Bruce Barclay, Assistant Chief Engineer, Global Inspection and Field Service

UL LLC

Any information and/or certification involving UL, Mark Service and/or products are provided on behalf of UL, LLC (UL) or any authorized licensee of UL. For questions, please
contact a local UL Customer Service Representative at www.ul.com/customer-service



CERTIFICATE OF COMPLIANCE

Certificate Number 20141219-EX26468
Report Reference EX26468-20141218
Issue Date 2014-DECEMBER-19

Issued to: Shandong Jintong Pipeline Co Ltd
No. 6, Yuhe Industrial Park
Weifang Shandong 261057 CHINA

This is to certify that
representative samples of

FITTINGS, RUBBER GASKETED
XGQT1, XGQT2, XGQT09

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 213 and ULC/ORD 213, Rubber Gasketed Fittings for
Fire-Protection Service.

Additional Information: See the UL Online Certifications Directory at
www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.

Barclay

Bruce Barclay, Assistant Chief Engineer, Global Inspection and Field Service

UL LLC

Any information and/or certification involving UL, Mark Service and/or products are provided on behalf of UL, LLC (UL) or any authorized licensee of UL. For questions, please
contact a local UL Customer Service Representative at www.ul.com/customer-service

